

GREG BELL Licutenant Governor

# State of Utah

### **DEPARTMENT OF NATURAL RESOURCES**

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

### Representatives Present During the Inspection:

OGM Karl Houskeeper



## **Inspection Report**

Permit Number:	C0070019		
Inspection Type:	PARTIAL		
Inspection Date:	Wednesday, September 15, 2010		
Start Date/Time:	9/15/2010 8:00:00 AM		
End Date/Time:	9/15/2010 3:00:00 PM		
Last Inspection:	Tuesday, August 24, 2010		

Inspector: Karl Houskeeper, Weather: Clear, Temp. 60 Deg. F. InspectionID Report Number: 2495

Accepted by: jhelfric

9/20/2010

Permitee: ANDALEX RESOURCES INC Operator: ANDALEX RESOURCES INC

Site: CENTENNIAL MINE

Address: PO BOX 910, EAST CARBON UT 84520-0910

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

**Current Acreages** 

6,528.83	<b>Total Permitted</b>
47.19	<b>Total Disturbed</b>
	Phase I
	Phase II
	Phase III

Mineral Ownership

**Types of Operations** 

✓ Federal ✓ Underground State ☐ Surface County ☐ Loadout Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Spoke with Dave Shaver at PFO before going to Centennial mine site. Dave not able to accompany the Division on site visit.

Inspector's Signature:

Karl Houskeeper,

Inspector ID Number: 49

Lous Ruse Date Wednesday, Septe



OIL, GAS & MINING

Permit Number: C0070019 Inspection Type: PARTIAL

Inspection Date: Wednesday, September 15, 2010

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	<b>V</b>		<b>✓</b>	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	<b>✓</b>			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	✓	✓		
6.	Disposal of Excess Spoil, Fills, Benches	<b>V</b>	✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	<b>✓</b>	<b>V</b>		
8.	Noncoal Waste	<b>V</b>			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	<b>✓</b>		<b>✓</b>	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other		П		

**Inspection Continuation Sheet** 

Permit Number: C0070019

Inspection Type: PARTIAL

Inspection Date: Wednesday, September 15, 2010

Page 3 of 3

#### 2. Signs and Markers

Mine identification signs are present at points of access to the permit area and contain the required information.

### 18. Support Facilities, Utility Installations

Visited several GVH (Gob Vent Holes) as part of the inspection.

The heads have been removed from the musk thistle located on GVH #1 and #5. Both sites are reclaimed.

Visited GVH 1, 5, 5a, 6, 11 and 12. GVH 1 and 5 are addressed above. Equipment is still present on GVH 6 and 11. GVH 6 and 12 each have a breach in the berm, but have treatment at the base of the breach and/or out slope of the pads. It appears that the breach's are located at low points in the pads and now serve as diversions.